



Nevada State Contractors Board  
***NEWS RELEASE***

[www.nscb.state.nv.us](http://www.nscb.state.nv.us)

---

***FOR IMMEDIATE RELEASE***

(702) 486-1100 x1139  
or (775) 688-1141 x1139

**CONTRACTORS BOARD TAKES DISCIPLINARY ACTION  
INVOLVING NINE CONTRACTORS**

*(Henderson, NV)* - At its meeting on August 17, 2005, the Nevada State Contractors Board adjudicated cases involving nine (9) contractors.

---

***Randy Robert Rivette, dba Rivette Construction***, license number 46718 (Carpentry) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; contracting in excess of established license limit; contracting with an unlicensed individual; failure to provide required Residential Recovery Fund disclosures; failure to establish financial responsibility; and failure to comply with a written request from the Board. The licensee was fined \$1,900.

---

***Mac Mar, Inc.***, license number 18044 (Residential and Small Commercial), 29332 (Plumbing and Heating), and 29333 (Electrical Wiring) based out of Henderson, Nevada was found in violation of Nevada Revised Statute 624 for contracting in excess of established license limit; acting in the capacity of a contractor under a name other than that set forth upon the license; and failure to respond to a written request from the Board. The licensee was fined \$7,200, assessed the cost of investigation, ordered to provide a current financial statement, and repair any substandard workmanship.

---

***Progressive Landscaping***, license number 56879 (Landscaping) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 willful disregard of building laws; acting in the capacity of a contractor beyond the scope of the license; failure to provide required Residential Recovery Fund disclosures; failure to comply with a written request from the Board; and failure to respond to a written request from the Board. The licensee was fined \$800, assessed the cost of investigation, ordered to submit to a Business Review.\*

---

***Talley & Sons Concrete, Inc.***, license number 41911A (Concrete Contracting) based out of Pahrump, Nevada was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The Board revoked the license of Talley & Sons Concrete, assessed licensee the cost of investigation, and required licensee to pay full restitution to all damaged parties.

---

**Roger Dale Flory dba Flory's General Contracting**, license number 42202 (Residential and Small Commercial) based out of Pahrump, Nevada was found in violation of Nevada Revised Statute 624 for bidding in excess of the limit place on the license by the Board; failure to establish financial responsibility; failure to comply with a written request from the Board. The Board revoked the license of Roger Dale Flory dba as Flory's General Contracting, assessed licensee the cost of investigation, and required licensee to pay full restitution to all damaged parties.

---

**J & R K M S Custom Flooring, Inc.**, license numbers 53092 (Terrazzo and Marble), 53093 (Finishing Floors), 53094 (Tiling), and 53361 (Finishing Carpentry) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; failure to establish financial responsibility; failure to comply with a written request from the Board; and failure to report to the Board a change in address or personnel. The Board revoked the licenses of J & R K M S Custom Flooring, Inc., required licensee to pay full restitution to all damaged parties, and assessed licensee the cost of investigation.

---

**Darrell Leon Alston, Jr. dba Dlaco Resurface**, license number 54100 (Permacrete) based out of Sun Valley, Nevada was found in violation of Nevada Revised Statute 624 substandard workmanship; failure to comply with the provisions of the regulations of the Board; failure to respond to a written request from the Board; failure to provide required Residential Recovery Fund disclosures; failure to establish financial responsibility; failure to comply with a written request from the Board; and failure to include license number and monetary limit on a contract or proposal. The Board revoked the license of Darrell Leon Alston, Jr. dba Dlaco Resurface, required licensee to pay full restitution to all damaged parties, and pay the cost of investigation.

---

**Beck Industries, Inc.** license number 40846 (Residential and Small Commercial) based out of Fredonia, Arizona was found in violation of Nevada Revised Statute 624 for combining with an unlicensed person to commit an unauthorized act; illegal lending of the license; failure to comply with a written citation; failure to establish financial responsibility; failure to comply with a written request from the Board. The Board revoked the license of Beck Industries, Inc., required licensee to reimburse the Residential Recovery Fund, and pay full restitution to all damaged parties, and assessed licensee the cost of investigation.

---

**JM Gair & Associates**, license number 26789A (Residential and Small Commercial) based out of Las Vegas, NV was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with the provisions of the regulations of the Board; failure to respond to a written request from the board; failure to establish financial responsibility; and failure to comply with a written request from the Board. The Board revoked the license of JM Gair & Associates, required licensee to reimburse the Residential Recovery Fund, and assessed licensee the cost of investigation.

---

**\*The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

---

*The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.*