



Art Nadler, Public Information Officer  
(702) 486-1100 x1139  
or (775) 688-1141 x1139

## **13 NEVADA CONTRACTORS DISCIPLINED BY CONTRACTORS BOARD**

*(Henderson, NV)* – At its meetings on Jan. 28 and 29, 2009, the Nevada State Contractors Board adjudicated cases involving 13 contractors.

---

***Robert John Boeddeker, dba R.J.B Systems Technology***, license number 52985 (Electrical Contracting) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with the terms of a construction contract, thereby causing material injury to another; failure to take appropriate corrective action; and failure to include the monetary license limit and license number on a contract or proposal. The licensee was fined \$2,500 and ordered to pay investigative costs.

---

***Coyote Development Corp.***, license number 62351 (Carpentry), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit and license number on a contract or proposal; bidding on a construction contract in excess of the limit placed on the license; acting in the capacity of a contractor beyond the scope of the license; willful disregard of the building laws of the state; failure to provide the name, license number, business address and telephone number of all subcontractors on the project; misrepresentation; failure to establish financial responsibility; and willful disregard of the laws of the state regarding industrial insurance. The licensee was fined \$4,450; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

---

***K.M.C. Builders, Inc.***, license numbers 59557 and 59559 (Pre-manufactured Housing, Residential & Small Commercial and Electrical), based out of Las Vegas, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to respond to a written request from the Board; failure to establish financial responsibility; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$4,750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The licenses were revoked.

---

**Monik Underground Construction, LLC.**, license numbers 56948 and 56949 (Concrete, Excavating Grading Trenching & Surfacing, Pipeline & Conduits) and **M.U.C.C. Corp., dba Monik Underground Construction**, license numbers 56948A and 56949A (Concrete, Excavating Grading Trenching & Surfacing and Pipeline & Conduits) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The licenses were revoked.

---

**Supreme Flooring, LLC.**, license number 68864 (Finishing Floors), based out of Bullhead City, AZ, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to respond to a written request from the Board; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit and license number on a contract or proposal; bidding on a construction contract in excess of the limit placed on the license; acting in the capacity of a contractor beyond the scope of the license; failure to notify the Board of a change in personnel or address within 30 days of the change; and failure to establish financial responsibility. The licensee was fined \$4,850; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

---

**Odilio Luigino Station, dba Silver State Iron.**, license number 46055 (Ornamental Metal), and **Silver State Iron, Inc.**, license number 46055A (Ornamental Metal) based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit and license number on a contract or proposal; failure to respond to a written request from the Board; failure to establish financial responsibility; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$3,850; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The licenses were revoked.

---

**St. Concrete, Inc.**, license number 59665 (Concrete), based out of Pahrump, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board and failure to establish financial responsibility. The licensee was fined \$1,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked

---

**Elwart Construction, Inc.**, license number 53215 (Residential & Small Commercial), based out of Fontana, CA, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

**R.C.D. Mechanical, Inc., dba Centsable AC & Heating**, license number 42123 (Refrigeration & Air Conditioning) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to pay money due for materials or services and failure to establish financial responsibility. The licensee was fined \$3,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

---

**Edward Grady Webb, dba E.W. Development**, license number 38784 (Residential & Small Commercial) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

---

**Bramble Homes, Inc.**, license number 41440 (Residential & Small Commercial), and **Bramble Development Group, Inc.**, license number 42240 (Residential & Small Commercial) based out of Las Vegas, NV, were found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500; ordered to pay investigative costs; provide a current financial statement and pay all money owing claims. The licenses were suspended.

---

**Calvert Construction, Inc.**, license number 41493A (Residential & Small Commercial), based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility; failure to discharge a lien; and misrepresentation. The licensee was fined \$500; ordered to pay investigative costs; provide a current financial statement and pay all money owing claims. The license was suspended.

---

**American Asphalt & Grading Co.**, license number 31785 (General Engineering), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with the regulations of the Board. The licensee was ordered to pay investigative costs.

---

**\*\*The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

---

*The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.*

---

###