

JIM GIBBONS
Governor

STATE OF NEVADA



STATE CONTRACTORS BOARD

MINUTES OF THE MEETING July 22, 2009

REPLY TO:

LAS VEGAS
2310 Corporate Circle
Suite 200
Henderson, Nevada 89074
(702) 486-1100
Fax (702) 486-1190
Investigations (702) 486-1110

www.nscb.state.nv.us

RENO
9670 Gateway Drive, Suite 100
Reno, Nevada 89521
(775) 688-1141
Fax (775) 688-1271
Investigations (775) 688-1150

MEMBERS
Guy M. Wells, Chairman
Kevin E. Burke
Michael Efstratis
John C. Ellison
Jerry Higgins
Nathaniel W. Hodgson, III
William "Bruce" King

CALL TO ORDER:

Hearing Officer King called the meeting of the State Contractors Board to order at 8:30 a.m., Wednesday, July 22, 2009, State Contractors Board, Henderson and Reno, Nevada. Exhibit A is the Meeting Agenda and Exhibit B is the Sign In Log.

BOARD MEMBERS PRESENT:

Mr. Bruce King, Chairman
Mr. Jerry Higgins
Mr. Nathaniel Hodgson

STAFF MEMBERS PRESENT:

Ms. Margi Grein, Executive Officer
Mr. George Lyford, Director of Investigations
Mr. Daniel Hammack, Chief of Enforcement

STAFF MEMBERS NOT PRESENT:

Mr. Chris Denning, Deputy Director of Investigations

LEGAL COUNSEL PRESENT:

Mr. Jonathan Andrews, Esq., Legal Counsel
Mr. David Brown, Esq., Legal Counsel

Ms. Grein stated the agenda was posted in compliance with the open meeting law on July 16, 2009 at Las Vegas City Hall, Sawyer State Building and Clark County Library. The agenda was also posted in both offices of the Board, Henderson and Reno and on the Board Internet Website.

ADJUDICATING BOARD MEMBER: BRUCE KING

1. DISCIPLINARY HEARING: (Continued from May 13, 2008) (Reno)

SIERRA CUSTOM CONCRETE, LLC, LICENSE NO. 67736

SIERRA CUSTOM CONCRETE, LLC, dba SIERRA POOLSCAPES, LICENSE NO. 70401

Licensee was not present.

Michael Kimmel, Esq. was present.

Two witnesses testified for the Board.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 4 – Letter from Michael S. Kimmel, Esq., dated July 21, 2009.

Exhibit 5 – Letter to surrender license numbers 67736 and 70401 from the Respondent dated July 21, 2009.

Exhibit 6 – Letter from Pezonella Associates, Inc., dated July 20, 2009.

Exhibit 7 – Letter from Blakemore Landscape Architecture dated July 21, 2009.

Hearing Officer King ordered Respondent to pay additional investigative costs that concurred from the May 13, 2009 Hearing and reimburse homeowner for the costs of the repairs. License numbers 67736, Sierra Custom Concrete, LLC and license number 70401, Sierra Custom Concrete, LLC, dba Sierra Poolsapces were revoked.

2. DISCIPLINARY HEARING: (Continued from May 13, 2009) (Reno)

STEVE HOEFT CONSTRUCTION, LICENSE NO. 43146B

Licensee was present.

Homeowners, Susan and Gordon Fath were present.

Three witnesses testified for the Board.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 2 – Copies of a set of plans.

Exhibit 3 – Copies of two bids.

Hearing Officer King found Respondent guilty of one (1) violation of NRS 624.3017(1) substandard workmanship; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.700(3)(a) failure to comply with Board's Notice to Correct; one violation of NRS 624.3013(5), as set forth in NRS 624.520(1) failure to provide Residential Recovery Fund notice to owner; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.640(5) each licensee shall include in all bids he submits or contracts he enters into for construction work within this State, the number of the license and any monetary limit placed upon his license; one (1) violation of NRS 624.3016(6) as set forth in NRS 624.600 name, license number, business address and phone number of all subcontractors with whom he has contracted with and all persons who furnish materials of the value of \$500.00 or more; one (1) violation of NRS 624.3011(1)(a) willful disregard of plans or specifications without the consent of the owner; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a fine of \$1,000.00 for each of the First and Sixth Causes of Action; a fine of \$500.00 for each of the Second, Fifth and Seventh Causes of Action; a fine of \$100.00 for the Third Cause of Action and a fine of \$250.00 for the Fourth Cause of Action, for total fines of \$3,850.00 and investigative costs in the amount of \$2,305.00. Fines and costs, with a financial statement that supports the license limit and compensation to the homeowners for repairs must be paid within (30) days of the July 22, 2009 Hearing date, or license number 43164B, Steve Hoeft Construction, Inc., shall be revoked.

3. DISCIPLINARY HEARING: (Continued from October 22, 2008, November 19, 2008 and December 18, 2008)

ADT CONSTRUCTION GROUP, INC., LICENSE NO. 53464

ADT CONSTRUCTION GROUP, INC., dba ADVANCED DEMOLITION TECHNOLOGIES,
LICENSE NO. 50051

ADT CONSTRUCTION GROUP, INC., dba S & G FIREPROOFING, LICENSE NO. 50081

LOGIC, LLC, LICENSE NO. 70943

Licensee was present with counsel, Evan James, Esq.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing file.

Exhibit 2 – Letter to the Board from Mr. Vasquez stating he will surrender license number 50051.

Exhibit 3 - Financial Statement sent to John Roberts dated July 22, 2009.

The case was taken under advisement. A written decision will be provided within two (2) weeks.

4. DISCIPLINARY HEARING:

MOAS ENTERPRISES, INC., LICENSE NO. 45878

Licensee was present.

Five witnesses testified for the Board.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 2 – Copies of checks to various subcontractors provided by Mr. Kanian.

Exhibit 3 – Estimates to complete the Kanian project.

Exhibit 4 – The Board's Notice to Correct dated June 29, 2007 for the Young project.

Exhibit 5 – Six (6) photos of the Young project taken by Board Investigator Greg Welch on May 12, 2008.

The following Respondent's Exhibits were entered:

Exhibit A – Respondent's Answer to the Board's Complaint.

This matter was continued for sixty (60) days to allow Western Roofing to make repairs.

5. DISCIPLINARY HEARING: (Stipulated Revocations)**a. BRUCE EDWARD HOLMES, dba BRUCE E. HOLMES, LICENSE No. 59608**

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 2 – Respondent's letter stipulating to the revocation of his license.

Hearing Officer King found Respondent guilty of one (1) violation of NRS 624.302(5) failure to respond to a written request from the Board; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a total fine of \$1,000.00 and investigative costs of \$1,319.00. License number 59608, Bruce E. Holmes, was revoked. Respondent was ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund plus fines and investigative costs prior to consideration of future licensure.

b. FANTASY CONSTRUCTION, INC., License No. 33803A

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 2 – Respondent's letter stipulating to the revocation of his license.

Hearing Officer King found Respondent guilty of one (1) violation of NRS 624.3013(3) failure to establish financial responsibility; one (1) violation of NRS 624.3013(4) failure to keep bond in force. Respondent was assessed a total fine of \$1,000.00 and investigative costs of \$1,472.00. License number 33803A, Fantasy Construction, Inc. was revoked. Respondent was ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund plus fines and investigative costs prior to consideration of future licensure.

c. FULL HOUSE CABINETRY, INC., License No. 60335

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 2 – Respondent's letter stipulating to the revocation of his license.

Hearing Officer King found Respondent guilty of two (2) violations of NRS 624.301(5) failure to comply with the terms of the construction contract, thereby causing material injury to another; one (1) violation of NRS 624.3012(1) diversion of money; one (1) violation of NRS 624.3013(5), as set forth in NRS 624.520(1) failure to provide Residential Recovery Fund notice to owner; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a total fine of \$4,000.00 and investigative costs of \$1,423.00. License number 60335, Full House Cabinetry, Inc. was revoked. Respondent was ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund plus fines and investigative costs prior to consideration of future licensure. It was acknowledged that Alfred P. Cormier, President of Full House Cabinetry, Inc., had filed personal bankruptcy on June 9, 2009.

6. DISCIPLINARY HEARING – DEFAULT ORDERS**a. SPACE CONSTRUCTION, INC., LICENSE NO. 64874, 63438**

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent Space Construction, license numbers 64874 and 63438, Kenny Seung Je, President and Qualified Individual in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Je was found guilty of one (1) violation of NRS 624.3013(3) failure to establish financial responsibility; one (1) violation of NRS 624.3018(2) certain persons are prohibited from serving as officer, director, associate or partner of licensee. Respondent was assessed a fine of \$1,000.00 for the First Cause of Action and investigative costs in the amount of \$1,223.00. License numbers 64874 and 63438, Space Construction, Inc. were revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

b. SANTIAGO URIBES ARTEAGA, dba S & S MASONRY, LICENSE NO. 32281

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent Santiago Uribe Arteaga, dba S & S Masonry, license number 32281, Santiago Uribe Arteaga, Owner and Qualified Individual, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Arteaga was found guilty of one (1) violation of NRS 624.3017(1) substandard workmanship; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.700(3)(a) failure to comply with Board's Notice to Correct; one (1) violation of NRS 624.301(2) abandonment of construction project when percentage completed is less than percentage of total contract paid; one (1) violation of NRS 624.3013(5), as set forth in NRS 624.520(1) failure to provide Residential Recovery Fund notice to owner; one (1) violation of NRS 624.3011(1)(b)(1) willful disregard of the building laws of the State; one (1) violation of NRS 624.3015(1) acting beyond scope of license; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a total fine of \$4,750.00 and investigative costs in the amount of \$1,393.00. License number 32281, Santiago Uribe Arteaga, dba S & S Masonry, was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

c. GOODWORK CONSTRUCTION, INC., LICENSE NO. 67611

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent Goodwill Construction, Inc., license number 67611, Joseph Aaron Jessop, President, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Jessop was found guilty of one (1) violation of NRS

624.3011(1)(b)(4) willful disregard of the industrial insurance laws of the State; one (1) violation of NRS 624.3013(4) failure to keep bond in force; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.640(3) failure to notify Board of change of address or personnel; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a total fine of \$2,250.00 and investigative costs in the amount of \$1,576.00. License number 67611, Goodwork Construction, Inc. was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

d. FEATHER RIVER CO., LLC, LICENSE NOS. 51323, 61022, 57133

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 2 – Respondent's e-mail to the Board acknowledging the Default order.

Hearing Officer King found Respondent Feather River De La Vega Construction, LLC, license numbers 51323, 61022, 57133, Eugene Lyle Gregory, Manager and Qualified Individual, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Gregory was found guilty of one (1) violation of NRS 624.3017(1) substandard workmanship; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.700(3)(a) failure to comply with the Board's Notice to Correct; one (1) violation of NRS 624.301(4) failure to prosecute a construction project with reasonable diligence; one (1) violation of NRS 624.301(5) failure to comply with the terms of the construction contract, thereby causing material injury to another; one (1) violation of NRS 624.3013(4) failure to keep bond in force; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility; one (1) violation of NRS 624.3018(2) certain persons are prohibited from serving as officer, director, associate or partner of licensee. Respondent was assessed a total fine of \$3,500.00 and investigative costs in the amount of \$3,495.00. License numbers 51323, 61022, 57133, Feather River Co., LLC, were revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

e. SHAWN ROBERT LINDEN, dba LINDEN PLUMBING, LICENSE NO. 44569

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent Shawn Robert Linden, dba Linden Plumbing, license number 44569, Shawn Robert Linden, Owner and Qualified Individual, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Linden was found guilty of one (1) violation of NRS 624.3012(3) failure to obtain the discharge or release of any lien recorded against the property; one (1) violation of NRS 624.3012(2) willful failure to pay any money when due for materials or service; one (1) violation of NRS 624.302(5) failure to comply with a written request by the Board; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.640(3) failure to notify Board of change of address or personnel; one (1) violation of NRS 624.3013(4) failure to keep bond in force; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a total fine of \$3,750.00 and investigative costs in the amount of \$1,429.00. License number 44569, Shawn Robert Linden, dba Linden Plumbing, was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

f. TIPTON ENTERPRISES, INC., LICENSE NO. 63510

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Exhibit 2 – Letter received from Stanley and Linda Tipton informing the Board they no longer reside in Nevada and will not be renewing their license.

Hearing Officer King found Respondent Tipton Enterprises, Inc., license number 63510, Stanley Dee Tipton, President and Qualified Individual, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Tipton as found guilty of one (1) violation of NRS 624.302(5) failure to respond to a written request by the Board; one (1) violation of NRS 624.3016(1) any fraudulent act committed in the capacity of a contractor, misrepresentation or omission of a fact; one (1) violation of NRS 624.3013(4) failure to keep bond in force; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a total fine of \$2,250.00 and investigative costs in the amount of \$1,499.00. License number, 63510, Tipton Enterprises, Inc., was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

g. BYRON DOUGLAS EVANS, dba HI TOP ROOFING, LICENSE NO. 58262

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent Byron Douglas Evans, dba Hi Top Roofing, license number 58262, Bryon Douglas Evans, Owner and Qualified Individual, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Evans was found guilty of one (1) violation of NRS 624.3017(1) substandard workmanship; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.700(3)(a) failure to comply with Board's Notice to Correct; one (1) violation of NRS 624.302(5) one (1) violation of NRS 624.302(5) failure to respond to a written request by the Board; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.640(3) failure to notify Board of change of address or personnel; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.640(5) each licensee shall include in all bids he submits or contracts he enters into for construction work within this State, the number of the license and any monetary limit placed upon his license; one (1) violation of NRS 624.3013(5), as set forth in NRS 624.520(1) failure to provide Residential Recovery Fund notice to owner; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a fine of \$3,500.00 and investigative costs in the amount of \$1,532.00. License number 58262, Byron Douglas Evans, dba Hi Top Roofing was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

h. G. C. ELECTRIC, INC., LICENSE NO. 43778A**G. C. ELECTRIC, INC., dba G. C. CONSTRUCTION GROUP, LICENSE NO. 58912**

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent G. C. Electric, Inc., license number 43778A and G. C. Electric, Inc., dba G. C. Construction Group, license number 58912, Gilbert Correa, President and Qualified Individual, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Correa was found guilty of one (1) violation of NRS 624.3013(3) failure to establish financial responsibility; one violation of NRS 624.3013(5), as set forth in NAC 624.640(3) failure to notify Board of change of address or personnel; one (1) violation of NRS 624.3018(2) certain persons are prohibited from serving as officer, director, associate or partner of licensee. Respondent was assessed a fine of \$1,000.00 and investigative costs in the amount of \$1,649.00. License number 43778A, G. C. Electric, Inc. and license number 58912, G. C. Electric, Inc., dba G. C. Construction Group were revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

i. REVOLUTION DEVELOPMENT, LLC, dba REVOLUTION CONSTRUCTION, LICENSE NO. 58069

REVOLUTION DEVELOPMENT, LLC, LICENSE NO. 65944

RESIDENTIAL DOORS AND MORE, LICENSE NO. 72345

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King summary suspended license number 58069, Revolution Development, LLC, dba Revolution Construction, license number 65944, Revolution Development, LLC and license number 72345, Residential Door and More, until the next Hearing date, August 26, 2009 when this matter will be continued.

j. B & C PLUMBING, INC., LICENSE NO. 50852

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent B & C Plumbing, Inc., license number 50852, Dena A. Knudson, President, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Ms. Knudson was found guilty of one (1) violation of NRS 624.302(5) failure to respond to a written request from the Board; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a fine of \$1,000.00 and investigative costs in the amount of \$1,339.00. License number 50852, B & C Plumbing, Inc., was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

j. RODNEY LEROY BEAN, dba SPORT COURT OF LAS VEGAS, LICENSE NO. 53467

Licensee was not present.

David Brown, Esq., recused himself from this matter.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent Rodney Leroy Bean, dba Sport Court of Las Vegas, license number 53467, Rodney Leroy Bean, Owner, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Bean was found guilty of one (1) violation of NRS 624.3014(1)(a) acting in the capacity of a contractor under a license issued under the name of the licensee; one (1) violation of NRS 624.3014(2)(a)(b)(c) aiding or abetting an unlicensed person to evade the provisions of this chapter; combining or conspiring with an unlicensed person to perform an unauthorized act; acting as agent, partner or associate of an unlicensed person; one (1) violation of NRS 624.302(5) failure to respond to a written request from the Board; one (1) violation of NRS 624.3013(5), as set forth in NRS 624.520(1) failure to provide Residential Recovery Fund notice to owner; one (1) violation of NRS 624.3015(1) acting beyond scope of license; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.640(5) failure for licensee in any material respect to include in all bids and contracts the license number and monetary limit placed on the license; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a fine of \$4,250.00 and investigative costs in the amount of \$1,559.00. License number 53467, Rodney Leroy Bean, dba Sport Court of Las Vegas, was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

k. ROBERT ALLEN NESHKOFF, dba ROBERT ALLEN BUILDERS, LICENSE NO 55795

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent Robert Allen Neshkoff, dba Robert Allen Builders, license number 55795, Robert Allen Neshkoff, Owner, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Mr. Neshkoff was found guilty of one (1) violation of NRS 624.3017(1) substandard workmanship; one (1) violation of NRS 624.3013(5), as set forth in NAC 624.700(3)(a) failure to comply with Board's Notice to Correct; one (1) violation of NRS 624.302(5) failure to respond to a written request from the Board; one (1) violation of NRS 624.3011(1)(b)(1) willful disregard of the building laws of the State; one (1) violation of NRS 624.3013(5), as set forth in NRS 624.520(1) failure to provide Residential Recovery Fund notice to owner; one (1) violation of NRS 624.3013(4) failure to keep bond in force; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a fine of \$4,000.00 and investigative costs in the amount of \$2,210.00. License number 56795, Robert Allen Neshkoff, dba Robert Allen Builders, was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

I. 702 SERVICES, LICENSE NO 60254

Licensee was not present.

The following Agency Exhibits were entered:

Exhibit 1 – Board Hearing File.

Hearing Officer King found Respondent 702 Services, license number 60254, Jodi Lyn Tuttle, President, in default and adopted the Findings of Fact and Conclusion of Law as set forth in the Administrative complaint. Ms. Tuttle was found guilty of one (1) violation of NRS 624.302(5) failure to

respond to a written request from the Board; one (1) violation of NRS 624.3013(3) failure to establish financial responsibility. Respondent was assessed a fine of \$1,000.00 and investigative costs in the amount of \$1,495.00. License number 60254, 702 Services, was revoked. Respondent was ordered to pay full restitution to the damaged parties and reimburse the Board for any monies paid out of the Residential Recovery fund plus fines and investigative costs prior to consideration of future licensure.

ADJOURNMENT

There being no further business to come before the Board, the meeting was adjourned by Hearing Officer Kings at 10:37 a.m.

Respectfully Submitted,

Janet Brinkley, Recording Secretary

APPROVED:

Margi Grein, Executive Officer

Bruce King, Hearing Officer