



Nevada State Contractors Board  
***NEWS RELEASE***

[www.nscb.state.nv.us](http://www.nscb.state.nv.us)

---

***FOR IMMEDIATE RELEASE***

Art Nadler,  
Public Information Officer  
(702) 486-1100 x1139  
or (775) 688-1141 x1139

**CONTRACTORS BOARD TAKES DISCIPLINARY ACTION  
INVOLVING FOUR CONTRACTORS**

*(Henderson, NV)* - At its meeting on November 16, 2005, the Nevada State Contractors Board adjudicated cases involving four (4) contractors.

---

***T C M Construction, Inc.***, license number 55659 (Roofing and Siding) based out of Las Vegas, NV. was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a written request from the Board; willful disregard of building laws; failure to include required Residential Recovery Fund disclosures on a contract or proposal; failure to respond to a written request from the Board; failure to include license number and monetary limit on a contract or proposal; combining with an unlicensed person to perform an unauthorized act; willful disregard of laws regarding industrial insurance; and misrepresentation of a material fact to obtain a license. The licensee was fined \$4,450, assessed the cost of investigation and ordered to pay restitution to the homeowners in the amount of \$11,800.

---

***Gerald Thomas Bryan, dba Gerald Bryan Construction***, license number 47543 (Residential and Small Commercial) based out of Las Vegas, NV. was found in violation of Nevada Revised Statute 624 for substandard workmanship; abandonment of a construction project; failure to respond to a written request from the Board; failure to include required Residential Recovery Fund disclosures on a contract or proposal; failure to establish financial responsibility; failure to comply with a written request from the Board; and failure to pay for materials or services. The Board revoked the license of Gerald Thomas Bryan, dba Gerald Bryan Construction, required the licensee to pay full restitution to all damaged parties in the amount of \$50,000, and assessed the cost of investigation.

---

***Owen Matthew Ondrisko, dba Stampco Concrete Construction***, license number 51041 (Concrete Contracting) based out of Henderson, NV. was found in violation of Nevada Revised Statute 624 for substandard workmanship. The licensee was ordered to repair substandard workmanship, or reimburse the homeowner.

---

## more ##

---

***Sunrise Painting Company***, license number 17587 (Painting and Decorating) based out of Las Vegas, NV. was found in violation of Nevada Revised Statute 624 for unauthorized use of license; permitting contracting business to be operated by an unlicensed individual; and combining with an unlicensed person to perform an unauthorized act. The Board revoked the license of Sunrise Painting Company, assessed licensee the cost of investigation, and required licensee to pay full restitution to all damaged parties.

---

*The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.*

---